

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Alexander
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		PERMIT NO.: SLAS-02-04
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE

Date of Site Inspection: August 15, 2014 Date of Last Inspection: June 11, 2014

FACILITY NAME AND ADDRESS:

Taylorsville Precast Molds, Inc.

Henry Road

Taylorsville, North Carolina 28681

GPS COORDINATES: N: 35.88222 W: 81.12165

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: David R. Mecimore Telephone: (828) 632-4608 Email: tpm@twave.net

FACILITY CONTACT ADDRESS:

128 Taylorsville Mfg. Road

Taylorsville, North Carolina 28681

PARTICIPANTS:

Charles Gerstell, NCDENR-Solid Waste Section

STATUS OF PERMIT:

A Permit to Operate a Septage Land Application Site was issued to Taylorsville Precast Molds, Inc. on December 6, 2011. This permit will expire on December 6, 2016.

PURPOSE OF SITE VISIT:

Follow-up Inspection

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

- 1. Proper signage was provided at the entrance to the facility. A second sign was provided on the east side of the property adjacent to Henry Road.
- 2. The access road leading to the site was of all-weather construction. Work has taken place to repair potholes and erosion noted on the previous inspection report. Continue efforts to repair damaged areas to ensure adequate access to the site.
- 3. The disposal boundaries were marked with white PVC pipes located at each corner of the application field. The damaged marker at the northwest corner has been repaired since the previous inspection. Thank you for your attention to this matter.
- **4.** During the previous inspection, a large area of dead vegetation was observed on the eastern portion of the application site. It appeared that this condition may have been the result of a grease burn due to inadequate dilution of grease waste. The area of dead vegetation was approximately 10-feet wide tapering to approximately 1-foot on each end and approximately 60-feet long. Inspection of the site on August 15, 2014 found vegetation beginning to take root in this area of concern. Continue efforts to ensure that this area is completely stabilized with the vegetation approved in the Nutrient Management Plan for the facility.
- 5. Hay has been harvested from the field since the last inspection.
- **6.** No evidence of runoff or application outside of the approved area was observed.
- 7. No evidence of rutting was observed.
- **8.** No objectionable odors were observed during the inspection.
- **9.** It appeared that all setbacks were being maintained.

Please contact me if you have any questions or concerns regarding this inspection report.

Charles T. Gerstell
Environmental Senior Specialist

Charles T. Huntell

Regional Representative

Sent on: <u>8/25/14</u>	X	Email		Hand delivery		US Mail		Certified No. []
-------------------------	---	-------	--	---------------	--	---------	--	------------------

Phone: (704) 235-2144

Copies: Jason Watkins, Western District Supervisor

Sarah M. Rice, Compliance Officer

Elizabeth Patterson, Environmental Technician, Composting & Land Application Branch